INSTALLATION INSTRUCTIONS

PSB-2029

PLASMA DISPLAY MOUNTING BRACKET

Prior to assembly, unpack carton completely and verify contents.
If you are missing any of the following components, please contact Customer Service at 1-800/582-6480



Figure 1



Figure 2



Figure 3

(2) Plasma Bracket
(4) 10-24 x ½ Button Head Cap Screw
(4) M5 x 20mm Phillips Head Cap Screw
(4) M6 x 30mm Button head cap screw
(1) M4 Allen Key
(4) Mounting Buttons – Tapped
(1) 1/8 Allen Key
(4) .875 OD x .33 ID x .375 Nylon Spacer
(4) M6 x 20mm Button Head Cap Screw

BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY

CAUTION!

PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

1. Using a 10-24 button head cap screw inserted from back side of bracket, secure mounting button, with chamfered hole of mounting button (larger surface) facing bracket, to bracket (four places) (see Figure 2 & Figure 3).
2. Place Nylon spacers over mounting holes on back of screen.
3. Attach mounting brackets to the display using the length of M6 screw that works best for your screen. (see Figure 4 & Figure 5).
4. With the aid of another person, lift your display up to the Chief Mount, aligning buttons of mounting brackets with slots in the Chief Mount.
5. Lower safety catch on the Chief Mount to secure your display, making sure latch is completely engaged.



Figure 4



Figure 5

CHIEF MANUFACTURING INC. 1-800-582-6480, Fax: 1-877-894-6918, Email: chief@chiefmfg.com
8804-000352 Rev. A
12/05/07